

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11, T3N, R9W, W.M.,
Tillamook County, Oregon.

ORIGINAL By Manius Buchanan, July 6, 1893.

Post; missing.

- 7" Hemlock bears N55°E 18 lks.; now a 22" badly rotted stump,
face closed.
- 8" Hemlock bears S08°E 26 lks.; now a 38" badly rotted stub,
8 ft. high with scribes 9W S11 visible.
- 10" Hemlock bears S70°W 71 lks.; missing.
- 15" Hemlock bears N25°W 53 lks.; missing, point falls in cat
road.

RESTORATION by unknown, unrecorded.

1 1/2" iron pipe; now rusted off at ground, upper portion laying
alongside.

15" Hemlock bears S70°W 37.7 ft.; exposed portions of scribes,
distance measured to face.

15" Hemlock bears N82°E 2.3 ft.; found blazes on all four
sides; distance measured to center of tree.

NOTE: corner was restored about 40 - 45 years ago by checking
ring count.

RESTORED October 23, 1987.

Var 21 1/2°E

Set a 1 1/2"x30" Aluminum pipe with 3 3/4" cap marked "STATE OF
OREGON DEPARTMENT OF FORESTRY T3N R9W S3 S2 S10 S11 1987 LS2272",
28 inches in ground, from which a:

29" Fir bears S22°E 42.6 ft. to face; scribed T3NR9WS11BT.

34" Hemlock bears S61 1/2°W 37.2 ft. to face; scribed
T3NR9WS12BT.

NOTE: no suitable trees within limits in north quadrants.


4"x4"x60" white painted Cedar post S42 1/2°E 2.8 ft. from corner pipe.
Metal location poster on new BTs.

Also poster on 15" Hemlock BT S70°W 37.7 ft.
Present and witnessed by Anthony J. Klosterman

Restored by



David B. Buchholz



BOOK 6