

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner for Sections 2 and 11, T1N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL By Henry Meldrum, September 16, 1884.

Post; missing.

5" Maple bears N51°E 10 lks.; missing, clump of vinemaple near this point.

12" Hemlock bears S06°E 21 lks.; now badly rotted windfall with no scribes visible.

RESTORATION by W.E. Anderson, March 8, 1932, (Book 4 and 69, Page 39 and 156 Tillamook County Records).

3"x3" Fir stake; missing.

36" Hemlock bears N38°W 19.0 ft.; now a 28" badly rotted stump with no scribes visible.

5" Vinemaple(Original) Rescribed in bark; see above.

RESTORATION by A.V. Benedict, RE1960, August 10, 1942 (Book 1, page 174 Tillamook County Records).

1"x65" iron pipe, 53" in ground; now bent and rusted, laying on ground.

36" Fir bears N85°E 31.7 ft.; missing.

RESTORATION by Richard A. Morris, LS401, May 12, 1958 (Book 1, page 327 Tillamook County Records).

1 1/2"x36" Galvanized iron pipe with 3" bronze cap, 33 inches in ground, in mound of stone; in place with 1" iron pipe by Benedict laying alongside.

22" Fir stump bears N09°E 141.3 ft.; now 22" with scribes 1/4 S2 BT RS401 visible.

42" Fir stump bears S13°W 119.5 ft.; now 42" with scribes 1/4 S11 BT visible on thin shell.

REWITNESSED December 22, 1987

Var. 21 1/2°E

From above pipe with marks "1987 LS1998" added, and from which a:

12" Fir bears N17 1/2°W 49.9 ft. to face; scribed 1/4S2BT.


11" Fir bears S19 1/2°E 104.0 ft. to face; scribed 1/4S11BT.

Metal location poster on new BTs.

Also poster on 42" Fir stump BT S13°W 119.5 ft.

3/4" brass washer marked "LS1998" nailed to face of new BTs. Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.  
David B. Buchholz, ES2272



BOOK 6  
340

