

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Line tree corner common to Sections 4 and 5, T3N, R10W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Manius Buchanan, June 23, 1893.

144" Cedar bears $N00^{\circ}13'E$ 8.00 chains from the one quarter
corner common to sections 4 and 5; now a 130" hollow stump, in
place, no notches visible.

RESTORED March 14, 1988

Var. $21\ 1/2^{\circ}E$

Set 1"x48" galvanized iron pipe with yellow plastic cap marked
"LS1998", 46 inches into center of stump, and from which a:

13" Hemlock bears $S67^{\circ}E$ 11.5 ft. to face; scribed APS4BT.

14" Hemlock bears $N19^{\circ}E$ 11.7 ft. to face; scribed APS4BT.

NOTE: Uphill side of stump was notched to allow pipe to be placed
in center, as stump is 10 ft. high and hollow.

Metal location posters on BT's.

Present and witnessed by David B. Buchholz and Clifford R. Foster.

Restored by



Anthony J. Klosterman

