

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 17, 18, 19 and 20, T2S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, July 21, 1891.

Post; missing.

10" Barberry bears N17E 29 lks.; missing.

6" Vine Maple bears N65 1/2W 65 lks.; missing.

22" Hemlock bears S23 1/2E 36 lks.; missing.

28" Hemlock bears S66 3/4W 27 lks.; Stump hole in place.

RESTORATION by Walter M. Robertson LS142 November 13, 1951 (Book 2, page 86, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground; in mound of stone; in place.

72" Fir stump bears S54E 139.0 ft.; now a 72" badly rotted stump with scribes T2S R7W S20 BT 142 visible.

89" Fir snag bears N68E 79.5 ft.; now a badly broken windfall with scribes T2 R7 S1 BT 42 visible.

NOTE: Distance measured from center of BTs.

REWITNESSED Septmeber 26, 1988

Var. 21 1/2E

From the above pipe with marks "LS1998 1988" added, and from which a:

10" Fir bears N80E 13.1 ft. to face; scribed T2SR7WS17BT.

10" Fir bears S34 1/2E 9.6 ft. to face; scribed T2SR7WS20BT.

12" Fir bears S81W 5.8 ft. to face; scribed T2SR7WS19BT.



10" Fir bears N18W 15.1 ft. to face; scribed T2SR7WS18BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buchholz under my direction.
David B. Buchholz, LS2272



4907 Third St.
Tillamook, Oregon 97141