

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

Section corner common to Sections 8, 9, 16 and 17, T3N, R9W, W.M.,
Tillamook County, Oregon.

ORIGINAL by Samuel G. Caudle, May 10, 1882.

Post; missing.

30" Hemlock bears N45W 71 lks.; missing.

14" Hemlock bears N20E 14 lks.; missing, found a 5/8" iron rod
at this position.

30" Hemlock bears S80E 11 lks.; now rotted remains of root
crown.

15" Hemlock bears S60W 7 lks.; missing.

RESTORATION by Manius Buchanan, June 28, 1893.

Post; missing.

3 lk. creek course SW bears S85-09E 2.34 chains; in place.

RESTORATION by Richard A. Morris LS401, June 15, 1970 (Book 5, page
45, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 31" in ground,
in mound of rock; in place, mound of rock missing.

29" Hemlock bears N45W 19.9 ft.; now a 30" stump with scribes
T3N R9W S8 BT visible.

42" Hemlock bears N62E 40.9 ft.; now a 42" badly rotted stump
with portions of scribes visible.

11" Hemlock bears S30E 22.4 ft.; now an 11" windfall with
portions of scribes visible.

24" Hemlock bears S13W 14.6 ft.; now a 24" stump with portions
of scribes T3N R9W S17 BT visible.

4"x4"x36" white painted Cedar post 1.0 ft. NE of corner pipe;
in place.

REWITNESSED December 28, 1988

Var. 21 1/2 E

From the above pipe with marks "LS1998 1988" added, and from which a:

11" Hemlock bears N22E 38.0 ft. to face; scribed T3NR9WS9BT.


30" Hemlock bears S37E 41.3 ft. to face; scribed T3NR9WS16BT.

14" Hemlock bears S05W 52.1 ft. to face; scribed T3NR9WS17BT.


Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by David B. Buchholz and Clifford R. Foster.



Anthony J. Klosterman



4907 Third St.,
Tillamook, Oregon