TILLAMOOK COUNTY SURVEYORS OFFICE

corner common to sections 17 & 20 T.3S., R.10W. W.M.

S17 1/4--+--S20 RS 287 1972

I set a 10" cast iron monument case around found 1 1/4" iron bar with 3" Tillamook County Brass cap set in 1972, see Tillamook County Surveyors rewitness #1035.

HISTORY OF FOUND MONUMENT

I found this corner to be as described on surveyors rewitness #1035 and it's accessory evidence found and/or set at that time to now be as listed below:

6" spruce S.40*41'E. 43.86', Now a stump.

17" spruce N.25*W. 32.12', Now 20" spruce face overgrown.*

"56" nail Westerly 1.10', found Okay.

"56" nail Southerly 1.20', now gone.

96" hat section post North 20.0', Now North 19.2'.*

New Accessory

"Monument spike" Southerly 1.79'

Monument location

This corner is located in the centerline of Galloway County Road. Approximately 1/2 mile West of it's junction with Sandlake County Road.

In the presence of Dan McNutt & Al Dvorak

March 8, 1989

Title allom & Duncan, C.S.

*Tillamook County Yellow metal location poster attached.

MAR 16 1989

OF TORS OF THE

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 14, 1967 ALLAN E. DUNCAN 793

an E. Turen

BOOK 6. 398