

-TILLAMOOK COUNTY SURVEYORS OFFICE

Southeast Corner of Webber Donation Land Claim #42
in
Section 1 T.1S., R.10W., W.M.

SE COR
WEBBER DLC
1971
RS 793

I set a 10" cast iron monument case around a 1 1/2" iron pipe with 3" brass cap, which I reset over the 1 5/8" iron bar set in 1971 as shown on Tillamook County Surveyors rewitness card #268, and encased in concrete.

History of found monument

I found this monument to be as described on the above said rewitness and the bearing trees and objects found and/or set at that time to now be as follows:

30" school mark spruce N.73*E. 56.68'; (Now 48" low cut stump N.69*E.).

*18" balm North 28.70'; (Now 19" balm N.4*W., bark scribing visible).

84" hat section post N.40*W. 22.25'; (Now missing).

1" hex iron rod S.1*01'W. 20.06'; (Now 1" hex iron pipe at distance).

3/4" iron pipe N.1*01'E. 20.06'; (found 3/4" inside diameter iron pipe, disturbed).

Maps of Reference not listed on Rewitness #268

B-749	1976	Harold Russell LS 707
B-810	1974	John L. Carlich LS 287
B-898	1980	Fredrick M. Gaylord LS 929
A-4444	1981	C. W. Cook LS 1098

New Accessory

*84" hat section post N.4*W. 22.3'

*indicates Tillamook County Surveyors location poster attached.

Monument Location

This monument is located approximately on the east bank of a creek in the centerline of Doughty County Road.

In the presence of Dan McNutt & Al Dvorak

April 1990

Title

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
2007-14-1987
ALLAN E. DUNCAN
793

APRIL 23, 1990

TILLAMOOK COUNTY
APR 23 1990
SURVEYORS OFFICE