TILLAMOOK COUNTY SURVEYORS OFFICE

Initial Point
Fourth Addition to Manzanita, Oregon
In Section 29 T.3N.,R.10W.,W.M

INITIAL
POINT
4TH.ADD
MANZANITA
1990

I found a 3" iron pipe with wood plug and brass screw 6" below the surface. I set a 3" Tillamook County brass cap on a 1 1/2"" iron pipe inside of the found iron pipe and encased in a 10" concrete cylinder.

History of Found Monument

The found 3" iron pipe described above is the original monument set for this subdivision on Tillamook County Surveyors map #C-190.

New Accessories

Power pole #294205 bears North 26.50'. The distance was measured to a finish nail with a brass washer in a scribed triangle on the East side of the pole.

16" spruce 5.70*E. 5.12'. The distance was measured to a finish nail with a brass washer in an axe blaze on the North side of the tree.

Location of Monument

This monument is located on the south side of Bonny Lane and on the East side of Bonny Lane at the toe of a small sandy cut bank.

In the presence of Dan McNutt & Al Dvorak

May 1990

Title:

TILLAMOOK COLL

SUPLEYORS OFFICE

4 1990

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON JULY 14, 1967 ALLAN E. DUNCAN 793

Allon & Duncon, c.s.

BOOK 6 475