

TILLAMOOK COUNTY SURVEYORS OFFICE

Section corner common to sections 25,26,35,&36 T.1S.,R.8W.,W.M.

T1SR8W
S26|S25
----+----
S35|S36
1952
RE 2311

I found a 1 1/2 " iron pipe with a 3" O.S.B.F. bronze cap in a mound of stones leaning down hill. I resurrected to vertical, and encased in a 10" concrete cylinder. (See Tillamook County Surveyors rewitness book 2 at page 236).

History of found Monument

I found this monument to be as reported on the above said rewitness, and the accessories found and/or set at that time to now be as follows:

40" snag 40' high, original 24" hemlock N.32*W. 29lks; (now 40" snag 15' high scribing visible).

3" spruce N.37*30'E. 61.1'; (now missing).

60" fir snag N.43*W. 23.0'; (now 60" snag 20' high N.43*W. 22.2' scribing visible).

*7" fir S.23*30'E. 92.1'; (found o.k. now 35" face overgrown).

*5" spruce S.29*W. 78.5'; (found o.k. now 42" face overgrown).

* Indicates yellow Tillamook County corner tag affixed.

Surveys and rewitnesses of reference:

A-418		W.E. Anderson	R.E.1697
B-632	1973	Richard A. Morris	L.S.401
F-40-317	1971	Richard A. Morris	L.S.401
Book 2 Page 236	1952	Louis W. Amort	R.E.2311

New Accessory

*72" light hat section post N.16*W. 1.9'.



Monument Location

This corner is located approximately 200' westerly of a spur ridge on a steep North slope. A.E.Duncan states, "At 5' West of corner begin steep descent to small creek, course N.10*W".

In the presence of Dan McNutt & Al Dvorak

July 1990

Title



Allan E. Duncan, C.S.

