

TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 corner common to section 35 T.3N.,R.9W.,W.M.
and section 2 T.2N.,R.9W.,W.M.

S 35
1/4--+--
S 2
1956
RE 2311

I set a 10" concrete cylinder around the found
O.S.B.F. 1 1/2" iron pipe with 3" bronze disk set
in 1956 from original evidence; (See Tillamook
County Surveyors rewitness book 2 page 337).

History of found monument

I found this corner to be as described on the above said
rewitness, and its' accessory evidence found and/or set at that
time to now be as listed below:

Original 6" hemlock S.25*W. 45 lks., reported on said rewitness
as a 12" stub 8' high scribes S BT visible; (now gone).

8" fir S.75*W. 45.8'; (now 21" stump 4' high, face overgrown.
O.D.F. yellow metal location poster attached inscribed "3N7").

26" cedar N.17*E. 149.9'; (now 38" cedar stump 5' high, face
overgrown, position not checked at this time. O.D.F. yellow metal
location poster attached).

42" fir snag N.66*E. 12.4'; (now a stump).

New Accessories

*5" fir S.15*W. 8.78'; scribed 1/4SB.T.

*7" fir West 7.95'; scribed 1/4SB.T.

*84" hat section post North 1.2'.

*indicates yellow Tillamook County location poster attached.

Monument location

This corner is located approximately 140' West of a small
creek, on a steep Easterly slope, in an approximately 8 year old
clear cut.

In the presence of Dan McNutt & Al Dvorak

July 1990

Title:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
793



BOOK 6 491