

TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 corner common to Sections 7 T.4S.,R.10W.,W.M.
and Section 12 T.4S.,R.11W.,W.M.

1/4
|
S12+S7
|
RS 287
1976

I found a 2" iron pipe with a 3" Tillamook County Surveyors brass cap, (see Tillamook County Surveyors rewitness card #723, and Tillamook County Surveyors map #B-1282).

History of found Monument

I found this monument to be as reported on the above said map (B-1282), and the accessories found and/or set at that time to now be as follows:

- *24" spruce uproot N.34*W. 10.0'; (Found, 24" uproot).
- *30" spruce uproot S.85*E. 7.8'; (Found, now 30" uprooted stump).
- 24" spruce S.17*W. 44.9'; (found, now a 24" spruce stump 5' high, scribing visible, U.S.D.A. location poster attached).
- 28" spruce S.30*E. 46.6'; (Found, now a 28" spruce stump 5' high, scribing visible, U.S.D.A. location poster attached).
- *96" hat section post West 1.0'; (Found, OK).
- * Indicates yellow Tillamook County corner tag affixed.

New Accessory

I set a 5/8"X10" iron rod with a red Tillamook County Surveyors plastic cap in the middle of a 29" spruce stump N.73*E. 24.87'.

I set a 5/8"X10" iron rod with a red Tillamook County Surveyors plastic cap in the middle of a 22" spruce stump S.4*E. 29.46'.

Maps of reference not listed on rewitness card #723

A-3478	1978	John L. Carlich	R.S.287
A-3518	1978	C. Wayne Cook	L.S.1098
B-828	1979	John L. Carlich	R.S.287
B-881	1979	Donald C. Cooley	L.S.1806
		& Kenneth A. Bauer	L.S.1803
B-1043	1982	Donald C. Cooley	L.S.1806
B-1282	1987	Jim S. Peterson	L.S.1084
A-5904	1989	Dudley M. Berry	L.S.1628

Monument Location

This corner is located on the North side of a recent clear cut, North of Sandlake-Woods County road.

In the presence of Dan McNutt & Al Dvorak

October 11, 1990

Title

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Allan E. Duncan, C.S.
OREGON
JULY 14, 1967
ALLAN E. DUNCAN
793