
## TILLAMOOK COUNTY SURVEYORS OFFICE

1/4 Corner common to sections 24 & 25 T.2N.,R.10W.W.M.



I found a 2" iron pipe with a 3" Tillamook County Surveyors brass cap in a 10" clay tile filled with concrete approximately 3" below the surface disturbed by field cultivation. I reset at vertical and drove to approximately 6" deep and added new concrete. The found BT checked very well as shown below.

## History of found monument

I found this monument to be as described on Tillamook County Surveyors rewitness #89 and the accessories found and or set at that time to now be as follows:

10" alder N.63\*W. 97.8' (Now gone).

22" spruce N.86\*W. 105.67'; (Now a 23" stump 4' high scribing visible on partially healed face).

\*84" hat section post East 296.0' (Found in the westerly R/W fence on Miami Foley County Road).

Surveys of Reference not listed on said rewitness

B-678	July 1968	Gene A. Leuthold	LS	475
B-763	6-23-77	Harold J. Russell	LS	707
B-770	10-3-77	Robert J. Olsen	LS	701
B-917	6-17-80	Colin H. Handforth		

New Accessory

\*4" diameter treated fence post N19\*E 34.65'

\*Indicates yellow Tillamook County Surveyors location poster attached.

Monument Location

This corner is located approximately 350 west of Miami-Foley County Road, approximately 50' North of a ditch line, and approximately 35' South of a fence line course Easterly and Westerly.

In the presence of Dan McNutt and Al Dvorak

January 10, 1991

Title:



PROFESSIONAL LAND SURVEYOR

OREGON JULY 14, 1967 ALLAN E. DUNCAN 7 9 3

allan & Guncan, c. 5.