

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter section corner common to Sections 7 and 8
T. 3N, R. 6W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing from which is:

- 50" Fir bears S54°E 24 lks.; now 50" stump, scribes $\frac{1}{4}$ " S BT visible.
- 20" Hemlock bears N27 $\frac{1}{2}$ °W 33 $\frac{1}{2}$ lks.; now 16" uproot, out of place, roots and root hole in place, scribes and face burnt off.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S7 S8 1955 RE 2311," 33 inches in ground, in mound of stone, and from which is:


- 12" Fir bears S79°E 7.0 ft.; scribed $\frac{1}{4}$ " S8 BT RE 2311.
- 6" Fir bears N31°W 9.8 ft.; scribed $\frac{1}{4}$ " S7 BT.

Oregon State Board of Forestry metal location poster on 12" Fir BT.

Set 4"x4"x72" white Cedar post 1.5' SW of pipe.

Dated February 1955

Restored by Richard A. Morris under my direction.
Richard A. Morris, Engr. Aide



Present and witnessed by Forrest Logan