

BAYSIDE SURVEYING

11765 HWY 101 South
Tillamook, Oregon 97141

Terry L. Jones
503-842-5551
Fax 503-842-5552

April 2002

REWITNESS

TOWNSHIP CORNER COMMON TO SECTIONS 36, 1 & 6
TOWNSHIP 2 and 3 SOUTH, RANGE 7 and 8 WEST
(Southeast corner of Township 2 South, Range 8 West)

I found:

OSBF brass cap stamped "T2S R8W S36 S1 T3S T3S S6 R7W 1975 RS 707",
top flush with ground. (See MAP B-714.)

From which:

4" x 4" white wood post bears Northwest 1'. (See MAP B-714.)

30" Fir with healed face bears S86 $\frac{1}{4}$ °W 13.7'. (12" Fir bears S86 $\frac{1}{4}$ °W
13.7'. See MAP B-714.)

18" Alder with bark scribing "T2S R8W S36 BT" bears N52°W 27.5'.
(10" Alder bears N52°W 27.5'. See MAP B-714.)

I Set:

An orange carsonite post 4' North

In the presence of Terry Jones, Dallas Esplin

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Terry L. Jones
OREGON
JULY 25, 1991
TERRY L. JONES
2507

