


**OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> 7		<b>TOWNSHIP:</b> 1 North		<b>RANGE:</b> 10 West	
<b>COUNTY</b> Tillamook				<b>DATE:</b> 2/20/2008	
<b>CORNER DESIGNATION:</b> Initial point of Pine Beach-Tillamook County Oregon				<b>(Please Check One)</b>	
				X	Condition Report Only
					Restoration
					Rewitness
					Not Found
					Reset
<b>Previous Rewitnesses, Restorations, Surveys, etc.:</b> Rewitness card #30-Tillamook County Survey Records; A-5178, A-7566, B-606, B-1218, B-1760, B-2170, C-91, C-466, C-494, P-173, P-271, P-432, P-546					
<b>Found Monument(s) and Accessories(Condition &amp; Source):</b> Found 2" iron pipe w/3" brass cap in 10" tile and cement in good condition. Found 84" hat section post bearing West 1.0' from corner/Yellow metal location tag reset on post. The 14" Pine being S. 50° E. at 6.43' noted in rewitness card #30 is now gone.					
<b>Monument Set(Procedures &amp; Description):</b> n/a					
<b>Other New Accessories Set:</b> Marked an X w/punch in east rim of manhole which bears N 75° 06' 04" E 24.99 ft. from corner.					
<b>New Bearing Trees:</b> n/a					
<b>Location &amp; Comments:</b> This corner is located 15' west of the west edge of Old Pacific Hwy. and north of Camp Magruder.				<b>Surveyor's Stamp</b> 	
<b>Firm/Agency:</b> Tillamook County Surveyor's Office					
<b>Address:</b> 201 Laurel Avenue-Tillamook, Oregon					
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor					
<b>Notes:</b>				Office Use Only	
<b>Witness(es):</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor Randy Wilson Survey Technician				