

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> The SE corner of Section 34, T1N, R10W,	<b>TOWNSHIP</b> 1 North, 1 South	<b>RANGE</b> 10 West
---	----------------------------------	----------------------


<b>COUNTY:</b> Tillamook	<b>DATE:</b> 04-30-08
--------------------------	-----------------------

<b>CORNER DESIGNATION:</b> The Section corner common to Sections 34, and 35, Township 1 North, Range 10 West, W.M., and Sections 2 and 3, Township 1 South, Range 10 West, W.M., Tillamook County, Oregon.	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th align="center" colspan="2">(Please check one)</th> </tr> <tr> <td><input type="checkbox"/></td> <td>Condition Report Only</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Restoration</td> </tr> <tr> <td><input checked="" type="checkbox"/></td> <td>Rewitness</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Unrecorded</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Reset at surface</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Referenced Out</td> </tr> </table>	(Please check one)		<input type="checkbox"/>	Condition Report Only	<input type="checkbox"/>	Restoration	<input checked="" type="checkbox"/>	Rewitness	<input type="checkbox"/>	Unrecorded	<input type="checkbox"/>	Reset at surface	<input type="checkbox"/>	Referenced Out
(Please check one)															
<input type="checkbox"/>	Condition Report Only														
<input type="checkbox"/>	Restoration														
<input checked="" type="checkbox"/>	Rewitness														
<input type="checkbox"/>	Unrecorded														
<input type="checkbox"/>	Reset at surface														
<input type="checkbox"/>	Referenced Out														

**Previous Rewitnesses, Restorations and Surveys, etc:** Section corner set on Map B-749, Tillamook County Survey Records.

**Found Monument(s) and Accessories (Condition & Source):** Found a 3" diameter Oregon State Board of Forestry Brass Cap in good condition, in tile and concrete, 0.90 feet below the surface. The monument is stamped as shown hereon.

(Map B-749) - Found the 41" (now 62") diameter Spruce tree at record position.  
 (Map B-749) - Found the 53" (now 72") diameter Spruce tree at record position, with healed face and Oregon State Board of Forestry metal location tag.  
 (Map B-749) -The 7" diameter Hemlock tree is now gone, apparently due to recent residential construction.  
 (Map B-749) - Power pole #5 has been replaced by a new power pole. The new power pole is not located at record position.  
 (Map B-749) - White painted cedar post is now gone.

<b>Monument Set (Procedures and Description:</b> Not applicable.	<b>Sketch of Found Monument:</b> 
--	---

**New accessories set:** Set a 60" hat section post with yellow metal location tag North 5.9 feet. I placed a 12" diameter plastic cylinder and 60 pounds of concrete around the metal post.

I established a tie to the section corner from the found centerline-centerline monument at Portland Ave. and 9<sup>th</sup> Street, holding the line between the found centerline monuments at Portland and 9<sup>th</sup> and Portland and 8<sup>th</sup>. I found 3" diameter Tillamook County Brass Cap stamped "CL - CL 1990" set on map A-6180, Tillamook County Survey Records. I turned an angle right of 90° 52' 20" at a distance of 29.80' from the centerline monument at Portland and 9<sup>th</sup> to the section corner. The found centerline-centerline monuments were in cast iron monument cases and in good condition. These monuments are perpetuations of those iron pipes set by W.E. Anderson as shown on map A-6087, Tillamook County Survey Records.

**New Bearing Trees set:** No new bearing trees set.

**Location & Comments:** This corner is located approximately 30' North of the centerline - centerline of Portland Avenue and 9<sup>th</sup> Street in Bay City.

<b>Firm / Agency</b> <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141
<b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Survey Supervisor
<b>Notes:</b>
<b>Witnesses:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor.

**SURVEYOR'S SEAL**

REGISTERED  
**PROFESSIONAL  
 LAND SURVEYOR**

Danny R. McNutt

OREGON  
 JULY 11, 2000  
**DANNY R. MCNUTT**  
 49230

RENEWAL 12-31-2008

