

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> East ¼ corner Section 12	<b>TOWNSHIP</b> 1 South	<b>RANGE</b> 10 West, 9 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 09-01-09
The East 1/4 corner of Section 12, Township 1 South, Range 10 West; and the West 1/4 corner of Section 7, Township 1 South, Range 9 West W.M., Tillamook County, Oregon.		<b>(Please check one)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input checked="" type="checkbox"/> Brass Cap set at surface
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> Rewitness Book 6, Page 393; Rewitness Book 5, Page 208; Rewitness Card #187; Survey maps A-11, A-49, A-150, A-271, A-742, A-952, A-4640, A-4641, B-56, B-148, B-205, B-535, B-3315, Tillamook County Survey Records.		<input checked="" type="checkbox"/> Referenced Out
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter Tillamook County Surveyor Brass Disk in a 10" cast iron monument case which is encased in concrete. This monument is now a subsurface monument and found to be as described in Rewitness Book 6, Page 393. The monument accessories for the subsurface monument were found to be in the same condition as described in said Rewitness Book 6, Page 393.		
<b>Monument Set (Procedures and Description):</b> Set a 2" diameter brass cap in concrete at the road surface. The monument was covered over during a recent asphalt paving project. The 2" diameter cap is stamped as shown hereon.	<b>Sketch of Found Monument:</b> <div style="text-align: center;"> </div>	
<b>New accessories set:</b> Two rock nails were set as reference points to the monument at 1.00' North and 1.00' East.		
<b>New Bearing Trees set:</b> No new bearing trees were set.		
<b>Location &amp; Comments:</b> This corner is located in the center of Alderbrook Road AKA Roosevelt Highway.		
<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor		
<b>Notes:</b> Digital images were taken of the set surface monument and subsurface monument.		
<b>Witnesses:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

