

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

BOOK 8 246

SECTION: 20, 21, 28 & 29	TOWNSHIP: 1 South	RANGE: 10 West
COUNTY: Tillamook		DATE: 4/30/2026
CORNER DESIGNATION: Section corner common to sections 20, 21, 28 and 29, Township 1 South, Range 10 West, Willamette Meridian.		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out

Previous Rewitnesses, Restorations and Surveys, etc...
BLM field note volume: OR-R0337 Page 0277.00 – 0278.00 (1890), A-876 (1958), Rewitness Card #310 (1977), B-771 (1977), A-8099 (2006), P-941 (2009), A-8388 (2011), B-3505 (2012), B-3635 (2014), Tillamook County Records.

History, condition, and sources
1890 (BLM field notes) set post for section corner and established 4 bearing trees for accessories. In 1977 (Rewitness Card #310) Found a 2" iron pipe badly rusted. No original Glo accessories were found. Only unrecorded Crown Zellerbach accessories were found. Surveyor's office then set a 2" iron pipe with 3" Tillamook County brass cap in cement and tile at position of found 2" iron pipe Stamped "T1SR10W S20 S21 S29 S23 RS 287 1977" as shown hereon. In 2012 (Rewitness Bk. 8, Pg. 004) set 4 new accessories to the corner. In 2026 Tillamook County Surveyor's dept. found a 3" Tillamook County brass cap in tile and concrete stamped as shown hereon. Found accessories are listed below.

Found: hat section post with yellow metal location tag East 1.0' (Rewitness Bk. 8, pg. 004, hat section post with YMLT East 1.5'), (Rewitness Card #310, hat section post East 1.5').

Found: white painted post with YMLT on ground next to monument (Rewitness Bk. 8, Pg. 004, white painted cedar post lying on ground near monument), (Rewitness Card #310, west 1.0').

Found: very rotted stub only one side remaining S56°E 19.20' (Rewitness Bk. 8, Pg. 004, Back cast only thing visible S56°E 19.2'), (Rewitness Card #310 25" dia. hemlock S56°E 19.20').

Found: 13" dia. hemlock with healed scar and YMLT S30°W 4.86' (Rewitness Bk. 8, Pg. 004, 10" dia. hemlock with scribing and a YMLT S30°W 5.0').

Found: 12" dia. hemlock with healed scar and YMLT S70°E 13.25' (Rewitness Bk. 8, Pg. 004, 10" dia. hemlock with scribing and a YMLT S66°E 13.30').

Found: 9" dia. hemlock with YMLT and healed scar N72°E 5.5' (Rewitness Bk. 8, Pg. 004, 8" dia. hemlock with scribing and a YMLT N72°E 5.5').

Found: 12" dia. fir with healed scar and YMLT N63°W 27.5' (Rewitness Bk. 8, Pg. 004, 10" dia. fir with scribing and a YMLT N63°W 27.8').

Yellow Metal Location Tag = YMLT
*For notes on corner see Field BK. MR 19 PG. 9-10, Tillamook County Surveyor's office.

New accessories set:

The Monument was tied conventionally using GPS established control in Oregon North Zone NAD 83/91 grid coordinates in US Survey feet. Coordinates provided hereon are given in WGS 84 Latitude and Longitude.

Latitude: 45°27'50.23186"
Longitude: -123°55'39.15094"



Location: ±500' NW from North End of Pond at quarry.

Tillamook County Surveyor office: 1510 3rd Street Suite C, Tillamook, OR. 97141

Party Chief: Travis Porter, Tillamook County Survey Technician III

Witnesses: Michael Rice PLS 86926, Tillamook County Surveyor
Kael Poklikuha, Tillamook County Survey Technician II

Notes: Digital images taken of monument and accessories.

SURVEYOR'S SEAL

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
DECEMBER 11, 2012
MICHAEL R. RICE
86926

RENEWAL 12-31-2026

BOOK 8 246