




OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT

Tillamook County Surveyor's Office

SECTION: 22	TOWNSHIP: 2N	RANGE: 7W	DATE: JUNE 21, 2016
COUNTY: TILLAMOOK			
CORNER DESIGNATION: SE Section corner Section corner common to Sections 22, 23, 27 and 26, T2N, R7W		(Please Check One)	
		<input checked="" type="checkbox"/> Condition Report Only	
		<input type="checkbox"/> Restoration	
		<input type="checkbox"/> Rewitness	
		<input type="checkbox"/> Not Found	
		<input type="checkbox"/> Reset	
		<input type="checkbox"/> Referenced Out	
Previous Rewitnesses, Restorations, Surveys, etc.: Rewitness Book 7, Page 163			
Found Monument(s) and Accessories(Condition & Source): FOUND OREGON STATE BOARD OF FORESTRY BRASS CAP ON 1 1/2" GALVANIZED IRON PIPE, STAMPED "T2N R7W S22 S23 S27 S20 1992 LS 1998 1951 199", BURIED 0.4', UNCOVERED; 34" (26") DOUGLAS FIR WITH HEALED FACE BEARS (N55° E 37.9'); 22" (14") DOUGLAS FIR WITH HEALED FACE BEARS (S52° E44.05'); 31" (21") DOUGLAS FIR WITH HEALED FACE BEARS (N58° W 56.1'); ROTTING 36" FIR SNAG, ±12 HIGH, 1/2 FACE WITH SCRIBING, BEARS (S85° E 37.5'); NO SUITABLE TREES TO SW THAT WOULD OUTLAST THE BRASS CAP, SEE REWITNESS BOOK 7, PAGE 163. 24" FIR SNAG WITH OLD FACE, NO SCRIBING, WITH OLD LOCATION TAG BEARS EAST 36', ORIGIN UNKNOWN.			
Monument Set(Procedures & Description):			
Other New Accessories Set: SET CARSONITE POST 1' EAST			
New Bearing Trees:			
Location & Comments: MONUMENT IS 60' SOUTH OF TOP RIDGE, 40' NORTH OF OLD CAT ROAD, 500' WEST OF RIVER.		Surveyor's Stamp  renewal date 6-30-17	
Firm/Agency: BAYSIDE SURVEYING			
Address: 11765 HWY 101 SOUTH TILLAMOOK, OR 97141			
Party Chief: TERRY JONES		Office Use Only 	
Notes: FILE NAME rewitness\T2N-R7W-S22-SW.xls			
Witness(es): TLJ/DWE			