

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: SOUTH ¼ OF 13 & NORTH ¼ OF 24	TOWNSHIP: 1 SOUTH	RANGE: 10 WEST
COUNTY: Tillamook		DATE: 7/18/18
CORNER DESIGNATION: QUARTER CORNER COMMON TO SECTIONS 13 & 24; TOWNSHIP 1 SOUTH, RANGE 10 WEST, W.M..		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out

Previous Rewitnesses, Restorations and Surveys, etc.. A-83 (1929), A-389 (1949), A-590, A-3832 (1975), A-2828 (1975), A-3471 (1978), A-4055 (1980), A-4136 (1980), A-4657 (1982), A-5215 (1985), A-6786 (1994), B-26, B-1843 (1995), B-1934 (1995), B-2180 (1998), B-2379 (2000), B-2758 (2004), B-3077 (2007), P-871 (2007), R/W BK 10 PG 21 (1888), R/W BK 10 PG 93 (1892), AMA BK 14 PG 93 (1892), AMA BK 15 PG 66 (1909), F-14-26 (1946), R/W BK 4 PG 70 (1949), R/W BK 1 PG 86 (1949), R/W BK 5 PG 54 (1965), R/W CARD #296 (1971), R/W BK 7 PG 414 (2007), TILLAMOOK COUNTY SURVEY RECORDS.
 R/W= REWITNESS

Found Monument(s) and Accessories (Condition & Source): FOUND 3" TILLAMOOK COUNTY BRASS CAP STAMPED AS SHOWN HEREON. IN 1898 A SPRUCE LIMB WAS SET TO MONUMENT THE QUARTER CORNER AND ACCESSORIES WERE SET. IN 1949 W.E ANDERSON SET A 2" PIPE BUT NO NEW ACCESSORIES. IN 1970 JOHN CARLICH FOUND THE 2" IRON PIPE AND SET 3 NEW ACCESSORIES. IN 1971 JOHN CARLICH SET A 2" IRON PIPE WITH A 3" TILLAMOOK COUNTY BRASS CAP STAMPED "1/4 13 24 1970" AND SET 2 NEW ACCESSORIES. IN 2007 DAN MCNUTT FOUND THE MONUMENT AND SET 1 NEW ACCESSORY.

(REWITNESS BK 7 PG 414) POWER POLE #6N61-L12 EASTERLY 1.16' GONE NOW POWER POLE #244800 NORTH 1' (REWITNESS BK 7 PG 414) 72" HAT SECTION MARKER WITH YELLOW METAL LOCATION TAG 3' EAST NOW 2.5'

() INDICATES RECORD INFORMATION, TILLAMOOK COUNTY SURVEY RECORDS.

NEW ACCESSORIES:
 MONUMENT WAS TIED DIRECTLY WITH GPS.
 WGS 84: LATITUDE: N 45° 28' 39"
 LONGITUDE: W 123° 51' 16"

Pictures of Found Monuments:



Location & Comments: MONUMENT IS LOCATED ±.5 MILE WEST ON MAKINSTER RD. FROM THE INTERSECTION OF HWY 101; ON THE SOUTH SIDE OF THE ROAD ±16' FROM CENTER OF THE ASBUILT ROAD.

Firm / Agency Tillamook County Surveyors Office
Address: 1510 3rd Street Suite C Tillamook, OR. 97141.

Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor

Notes: Digital images taken of monument and accessories.

Witnesses: Michael Rice, P.L.S. 86926, Tillamook County Surveyor
 Travis Porter, Survey Tech.

SURVEYOR'S SEAL

