

INDEX FILE NO. G-13 CORNER RECORD (SEARCH) Tract or Survey No. G-13
 Filed 35 R. 10W.D. Hebo County TILLAMOOK # 602
 Merid. LL V.F. SIUSLAW State ORE
 CORNER LOCATION
 DESCRIBE CORNER MONUMENT FOUND
 GLO 1882 SET A POST AND MARKED:
 A 10" Hem., N. 85° E., 16 LKS.
 A 8" Hem., S. 28° W., 30 LKS.
 DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND A CEDAR POST WITH PROPERTY BOUNDARY TIN ATTACH
 ALONGSIDE 1/2" PIPE.
 FOUND A SMALL 1X3 SLAB STILL STANDING WITH MKS.
 1/4 S.BT., S. 28° W., 30 LKS. AS IN RECORDS.
 PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 PLANE COORDINATE POSITION
 State _____ Zone _____
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 FOUND 20" BLOWN DOWN Hem., N. 85° E., 16 LKS. WITH HEAL
 WITNESS FACE.
 THE POST AND PIPE HAD BEEN SET BY USFS 1946.
 Signature _____ Date _____
 Division _____ Headquarters _____
 Leonard Whitmore
 Timber Nib
 6-15-68
 7100-52
 REV. 65

CORNER RECORD (PERPETUATION)
 MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 I MARK 2 NEW BT'S:
 10" Hem., N. 31° W., 10³ FT. MKD. 1/4 S 9 BT.
 6" Hem., S. 42° E., 14⁴ FT. MKD. X BT.
 Leonard Whitmore
 Work Done By _____ Title _____ Date _____
 State Registration No. _____
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____
 REMARKS
 Index File No. T 35 R 10W M. Tract or Surv. No. 1/4 Cor. 914
 12
 13